

	Type	L #	Hits	Search Text	DBs	Time Stamp	Error Count	Definition
1	BRS	L1	43984	(pattern\$3 same (Ti or titanium or Al or aluminum or Ta or tantalum or "hard mask")) and etch\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:49	1	The search/retrieval could not be aborted because
2	BRS	L8	14096	(pattern\$3 near5 (Ti or titanium or Al or aluminum or Ta or tantalum)) and etch\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:55	0	
3	BRS	L15	5262	8 and 438/\$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:58	0	

	Type	L #	Hits	Search Text	DBs	Time Stamp	Error Count	Defects	Error in iteration
4	BRS	L22	9018	(pattern\$3 near5 (Ti or titanium or Al or aluminum or Ta or tantalum)) and etch\$315 and (plasma or dry or rie or ("reactive ion" adj etch\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:49	1	0	Truncation overflow.
5	BRS	L23	9011	8 and (plasma or dry or rie or ("reactive ion" adj etch\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:49	0	0	
6	BRS	L30	3855	23 and 438/\$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:50	0	0	
7	BRS	L37	1658	30 and @pd<=19970120	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:58	0	0	
8	BRS	L44	830	(pattern\$3 near5 ((Ti or titanium or Al or aluminum or Ta or tantalum) adj5 mask)) and etch\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:56	0	0	
9	BRS	L51	300	44 and 438/\$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:58	0	0	
10	BRS	L58	91	44 and 216/\$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:58	0	0	

	Type	L #	Hits	Search Text	DBs	Time Stamp	C o m m e n t s	E r r o r D e f r o r e r s
11	BRS	L65	155	51 and @pd<=19970120	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 17:39		0
12	BRS	L72	56	58 and @pd<=19970120	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 16:59		0
13	BRS	L82	138	65 not 72	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/11/15 17:39		0